

---

**From:** Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFF136]  
**Sent:** 7/14/2014 7:53:40 AM  
**To:** David Bristow (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=David41]  
**CC:** Diane M Simon (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Diane51]; John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=John171]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]  
**Subject:** PP 2Q14 Ash Pond Assessment  
**Attachments:** PP-Ash Pond Assessmnt-2Q14.doc

Dave,

Attached is the 2Q14 Ash Pond inspection. Sorry for the delay.

Power Generation, Corporate Environmental, and the station are working to obtain the necessary permits and then begin PO and vendor selection. Not sure when this will be completed, the process is taking longer than expected.

A new slough has been identified on the inside slope of D Pond, same area as the previous repair. Power Gen Engineering has been notified and is monitoring the area.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)